


## **CASE HISTORY**

No. 1614



# **Expected Total Loss at Offshore Madura Strait, INDONESIA**



### The Challenge

Madura Strait has common problem with Total Losses issue. Many offset wells has a similar case. Estimate losses will encountered at 6 1/8" section at 7,241 ft - 7,752 ft MD. Operator has a strategy to prevent the losses with proactive treatment

#### **The Action**

Once started drilling 6 1/8" section, DRIL-EZY with 5 ppb at active system and Sweep Hi Vis with 10 ppb DRIL-EZY every 2 stands . Spotting Pill material stand by at RIG site without pumping to the well

#### The Result

Drilling was continued with good ROP without any losses recorded Geologies confirmed at casing point, no losses recorded and hole was stable.



The information in this bulletin is believed to be accurate, but all recommendations are without warranty, since the conditions of use are beyond our control. The listed properties are illustrative only, and notproduct specifications. Pt Obm DRILCHEM disclaims any liability in connection with the use of this information, and does not warrant against infringement by reason of the use of any of its products in combination with other materials or in any process.